

## **SKIDOME Ski & Board - THINGS TO DO AFTER THE SEASON IS OVER**

Now that it is warmer out, Take an hour and clean the gear and equipment.  
Do not use laundry Detergent.

Any type of fabric can become damaged from its contact with chloride salts (perspiration). Chloride salts, when left on a fabric, can bleed dyes, slowly discolor and eventually deteriorate a fabric.

### **SKIS / BOARD**

---

*BATH TIME*- Rinse with cold water, in the shower or by hose, then dry

*BINDINGS* – Record DIN (binding setting) on a tag and attach to ski  
Use a screwdriver to back off, reduce the setting to Zero

*EDGES* – Use ZARDOZ NOTwax with rust block, or wax on edged to protect  
Do not store in humid damp area.

### **BOOTS**

---

Perspiration salts build up and ruin fabrics. Do not use laundry Detergent.

*BATH – LINERS*: Take out orthotics or foot bed, remove liners. Use cold water and fill up boot. Use a combination of oxy clean and borax in water. Rinse 3 times. Dry outside and use a hair dryer 2 times a day over multiple days to dry.

*SHELL* – Wash with cold water

*FUNK* – Pick up OT Oder Spray. ODER OUT or other sports spray designed for hockey pads

### **JACKET, SHELLS, PANTS, BIBS**

---

Product: NIKwax [www.nikwax.com](http://www.nikwax.com)

Tech Wash – Non Detergent wash

TX – DIRECT Spray Waterproof

Reference: <http://www.skijacketcleaning.com/>

Remove items from gear

Follow directions on Nikwax Tech Wash

Use in bath tub or in 20 lb washer

Alternative for NIKWAX wash:

Non Detergent mix - Bath Tub of warm water, 2 cups of Baking Soda, and 2 cups Borax.

Agitate by hand every 5 mins for 15 mins. Drain, Rinse 2 times. If you would rather go to a Laundry and use a 20lb machine.

Spray on waterproof to finish. Follow Directions.

Dry in tumble dryer on Low to Medium follow label directions

### **HELMET**

---

Clean with a mix of water, baking soda, and borax, Rinse 3 times, wipe and let dry.